IMPORTANT INFORMATION ABOUT YOUR DRINKING WATER Drinking Water Contains High Levels of Disinfection By-Products

NOTICE OF STANDARD MAXIMUM CONTAMINANT LEVEL ("MCL") VIOLATIONS

	NOTICE OF STRIKE	11100 111111111111111111111111111111111	JOI(1111/11/11/11/11/11/11/11/11/11/11/11/1	(,	
The Exeter Water Dept water system recently violated drinking water standards. Although this is (name of water system) not an emergency, as our customers, you have a right to know what happened, what you should do, and what we are doing to correct this situation.					
anı	e are required to monitor your dr nual average ("LRAA") standard 0.060 mg/L. Testing results for t	l for Total Trihalomet			
	orrected 3rd quarter of (calendar quarter(s)) Total Trihalomethanes and/or H	(year(s))			contaminant level
	Contaminant Name mathematical error corrected	Sampling Site: (fill in site ID)	Sampling Site: (fill in site ID)	Sampling Site: (fill in site ID)	Sampling Site: (fill in site ID)
	Total Trihalomethanes	0.082 mg/L (fill in LRAA value)	0.097 mg/L (fill in LRAA value)	0.094 mg/L (fill in LRAA value)	mg/L (fill in LRAA value)
	Haloacetic Acids	mg/L (fill in LRAA value)	mg/L (fill in LRAA value)	mg/L (fill in LRAA value)	mg/L (fill in LRAA value)
What does this mean?					
This is not an emergency. If it had been you would have been notified immediately. However, some people who drink water containing trihalomethanes in excess of the MCL over many years may experience problems with their liver, kidneys, or central nervous system, and may have an increased risk of getting cancer. Some people who drink water containing haloacetic acids in excess of the MCL over many years may have an increased risk of getting cancer.					
What should I do?					
It is not necessary to use alternate water; however, if you have specific health concerns, please contact your health care professional. General health related questions may be directed to Dave Gordon of the DES Environmental Health Program at (603) 271-4608.					
Steps We Are Taking: A new carbon slurry system has been installed and (describe corrective action such as hiring a consultant, investigating treatment options, etc.) been added to 2 of the 3 storage tanks — further process					
rei	finement are being	investigated.	• •		
We a	inticipate resolving the problem		•	For more information	on, please
conta	rtact Paul A. Roy, P.E. of Exeter Water Dept at 603-772-1346				
or _	(name of water system contact) 13 Newfields Rd Exet address)	(name of syste	em or company)	(telephone #)	•
r	lease share this information wit eceived this notice directly (for his by posting this notice in a pu	example, people in ap	partments, nursing h	omes, schools, and bi	

0801010

PWS ID:__

___ Date Distributed: ___January 9, 2015